

ABSTRACT OF THE DISCLOSURE

5 A method of joining a wire includes the steps of: providing the wire having a conducting portion consisting of a plurality of core wires, restricting a width of the conducting portion, pressing the core wires of the conducting portion restricted in the restricting step, and joining the pressed core wires of the conducting portion each other so that the conducting portion is integrally formed into a flat plate-shape.